Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

KB1410 OVERHEAD CABLE NY Spills S103482833
North 37-18 QUENTIN RD N/A

> 1 1.778 mi.

9386 ft. Site 2 of 2 in cluster KB

BROOKLYN, NY

 Relative:
 SPILLS:

 Higher
 Name:
 OVERHEAD CABLE

 Actual:
 Address:
 37-18 QUENTIN RD

 19 ft.
 City, State, Zip:
 BROOKLYN, NY

Spill Number/Closed Date: 9804845 / 2002-11-05

 Facility ID:
 9804845

 Facility Type:
 ER

 DER Facility ID:
 74431

 Site ID:
 80283

 DEC Region:
 2

Spill Cause: Equipment Failure

 Spill Class:
 C3

 SWIS:
 2401

 Spill Date:
 1998-07-18

 Investigator:
 CAENGELH

 Referred To:
 Not reported

 Reported to Dept:
 1998-07-18

 CID:
 370

Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported

Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 1998-07-18
Spill Record Last Update: 2002-11-05
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999

Contact Name: ABOVE CALLER

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

ENGELHARDT e2mis no. 118-424: AT POLE #47973 F/O #3718 QUENTIN RD

FOUND THAT OIL LEAKED FROM AERIAL FEEDER CABLE ONTO THE SIDEWALK (AN

AREA 4' X 3' STAIN) AND THERE ARE DROPS ON A PRIVATE CAR. LIQUID IS

CONTAINED TO THIS AREA AND NO SEWERS OR WATERWAYS AFFECTED. JOINT WAS WRAPED TO STOP FUTURE LEAKS. CLEANUP TO BEGIN ASAP. CONSUMER HAD CAR

CLEANED AND WILL FILE A CLAIM WITH COMPANY.NO SAMPLE TAKEN AND NO E.S.TAG PLACED. OIL CLEANUP TO BE TREATED AS A LESS THEN A 50 PPM. APPROX AMOUNT OF OIL LEAKED 1 PINT. UPDATE 18-JUL-98 CLEAN UP COMPLETED WITH DIAPERS, ABSORBANT AND SLIX AT 14:00 HRS"

"1 PINT SPILL TO A CAR AND SIDEWALK SPILL CONTAINED AND CLEANUP IN

PROGRESS"

All Materials:

Remarks:

 Site ID:
 80283

 Operable Unit ID:
 1062751

 Operable Unit:
 01

 Material ID:
 319607

 Material Code:
 0541A

 Material Name:
 dielectric fluid

Map ID Direction Distance Elevation

Site

MAP FINDINGS

Database(s) EPA I

EDR ID Number EPA ID Number

Case No.: Not reported Material FA: Petroleum Quantity: 1.00 Units: G
Recovered: .00

Oxygenate: Not reported